

Applanation Tonometer Compatibility Chart

AT-1					AT-2			
								
		Calibrator (Included)	Measuring prism (Included)	Tonometer base (Option)		Calibrator (Included)	Measuring prism (Included)	Tonometer base (Option)
700GL	☐	☐	☐	TB700				
700GL NSW	☐	☐	☐					
30GL	☐	☐	☐	TB30				
4ZL	☐	☐	☐	TB700	☐	☐	☐	TB2
2ZL	☐	☐	☐		☐	☐	☐	
装着方法	Install AT-1 by attaching the tonometer base to the top of the slit lamp microscope. When not in use, AT-1 can be stored on the left or right side of the microscope.				Install AT-2 by attaching the tonometer base to the top of the slit lamp microscope. When not in use, AT-2 can be stored by folding the prism holding arm upward and rotating the main body 90° to the left (from the user's perspective).			

Although product performance has been verified through rigorous testing, equipment should be regularly inspected using the supplied calibrator (check weight/check weight holder) to ensure appropriate pressurisation before use.